

PORT OF FLEETWOOD

NOTICE to MARINERS 03 of 2017

No.6 buoy

Mariners are hereby advised that it has been reported that the top section of No.6 buoy has broken away in the weather and has been reported moving upstream on the River Wyre.

Mariners are further advised to navigate with extreme caution until such time as the unlighted lower part of the buoy has been recovered and a replacement buoy placed back on station.

Mariners are requested to keep a sharp lookout for the top part of the buoy, and to report any sightings to Fleetwood Docks Radio on vhf ch 12 or by leaving a message on 01253 872 351 if the Lockhead is shut and no response is received.

ABP Fleetwood
Port Office
Fleetwood
Lancashire
FY7 6PP

Captain Guy Lockwood
Harbour Master

13th January 2017