



PORT OF FLEETWOOD

NOTICE to MARINERS 04 of 2017

No. 3 buoy reported unlit

Mariners are hereby advised that the No.3 buoy has been reported and confirmed as unlit.

Mariners are therefore advised to navigate with extreme caution until such time as the light has been repaired.

ABP Fleetwood
Port Office
Fleetwood
Lancashire
FY7 6PP

Captain Guy Lockwood
Harbour Master

16th January 2017

Owners, Agents, Charterers, Fishermen and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the masters or persons in charge of their vessels or craft.