



PORT OF FLEETWOOD

NOTICE to MARINERS 11 of 2018

No. 7 buoy off station

Mariners are hereby advised that the No.7 buoy has broken away from its charted position and was last sighted drifting to the SE of Fleetwood dock channel.

Mariners are therefore advised to navigate with extreme caution until such time as this buoy can be recovered.

ABP Fleetwood
Port Office
Fleetwood
Lancashire
FY7 6PP

David Taylor
Deputy Harbour Master

17th August 2018

Owners, Agents, Charterers, Fishermen and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the masters or persons in charge of their vessels or craft.