



PORT OF FLEETWOOD

NOTICE to MARINERS 11 of 2021

FLEETWOOD No 23 buoy unlit

Mariners are hereby advised.

That the Fleetwood No23 buoy at the entrance to Fleetwood dock channel has been reported unlit.

All mariners are advised to navigate with caution when passing this area.

For any further information please contact Fleetwood dock on vhf channel 12 during tide times.

LNtM No 9 of 2021 is now cancelled.

ABP Fleetwood
Port Office
Fleetwood
Lancashire
FY7 6PP

Dave Taylor
Deputy Harbour Master

27th May 2021

Owners, Agents, Charterers, Fishermen and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the masters or persons in charge of their vessels or craft.